HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

PEARL HARBOR MEMORIAL COMMUNITY CHURCH

HABS HI-508

(Moanalua Community Church)

(Pearl Harbor Navy Complex, Moanalua, Facility No. 2602)

20 Bougainville Drive

Honolulu

Honolulu County

Hawaii

INDEX TO BLACK AND WHITE PHOTOGRAPHS

David Franzen, photographer, August 2004

HI-508-1	Front elevation, view facing northwest
HI-508-2	Tight oblique view of stained glass wall panel and southwest wing, view facing north
HI-508-3	Oblique view of the northwest end of the rear facade showing structural glue-laminated beams, view facing southeast
HI-508-4	Rear of the church and pavilion addition, view facing southeast
HI-508-5	Oblique view of southwest facade of church, rear of southwest wing, and pavilion, view facing northeast
HI-508-6	Oblique view of front and northeast facade, preschool in background, view facing southwest
HI-508-7	Interior elevation, view down aisle toward alter, view facing northwest
HI-508-8	Interior elevation with view of stained glass wall panel, view facing southeast
HI-508-9	Interior, detail of choir area and lava rock planter, view facing northwest
HI-508-10	Interior detail of wood sliding doors on the northeast, side view facing northwest